

EVALUATION REPORT

**TENDER FOR SERVICE & MAINTENANCE/REPAIR CONTRACT OF ALL SPLIT & PACKAGE TYPE AIR CONDITIONERS,
WITH PARTS, WITHOUT PARTS & SUPPLY WITH INSTALLATION OF REQUIRED PARTS (NEED BASIS)
AGAINST ADVERTISED NO.AMS (W)/69608/MH., DATED 12-11-2021, OPENED ON 09-12-2021.**

BID ENQUIRY NO.	NAME OF TENDER	ESTIMATED PRICE	ESTIMATED BID SECURITY 2%	NO. OF BIDS	WINNER FIRM	TECHNICAL STATUS	QUOTED RATE	LOWEST BID COST	FINAL BID STATUS
1.	TENDER FOR SERVICE & MAINTENANCE/REPAIR OF ALL SPLIT & PACKAGE TYPE AIR CONDITIONERS, DIFFERENT CAPACITY I.E. 1 TON,1.5 TON,2 TON, 5HP,10HP,15 HP & 20 HP ETC. (WITH & WITHOUT PARTS, & SUPPLY WITH INSTALLATION OF REQUIRED PARTS (NEED BASIS) ON ANNUAL CONTRACT BASIS FOR THE PERIOD OF ONE YEAR EXTENDABLE FOR THREE MONTHS.	5,000,000/-	Rs. 100,000/-	01	M/s Tariq Zia & Co.	Responsive	3408127	3408127	Responsive

List of Parts
Rates Offered by M/s Tariq Zia & Co. (Need Basis)

SR:#	NAME OF ITEMS WITH SPECIFICATION	QUOTED RATES (RS.) (M/S Tariq Zia & Co.)
1.	Washing / General Service Charges Pump Down (1 Ton to 2 Ton)	1050
2.	Washing / General Service Charges (5 H.P)	1500
	Washing / General Service Charges (10 H.P)	2000
	Washing / General Service Charges (15 H.P)	2200
	Washing / General Service Charges (20 H.P)	2500
3.	Washing / General Service Charges Package Type (5 H.P to 20 HP)	2500
4.	Leakage Removal & Gas Charging (1 Ton to 2 Ton)	4500
5.	Leakage Removal & Gas Charging (5 H.P)	6500
	Leakage Removal & Gas Charging (10 H.P)	9500
	Leakage Removal & Gas Charging (15 H.P)	9500
	Leakage Removal & Gas Charging (20 H.P)	10500
6.	P.C.B Kit Repair with Remote (1 Ton to 2 Ton)	2500
	P.C.B Kit (New) with Remote (1 Ton to 2 Ton)	4500
7.	P.C.B Kit Repair with Remote (5 H.P to 10 HP)	3500
	P.C.B Kit (New) with Remote (5 H.P to 10 HP)	6500
	Thermostat Repair (10 H.P to 20 HP)	2200
	Thermostat Replace (10 H.P to 20 HP)	7550
8.	Indoor Blower Motor (1Ton to 2 Ton)	
	i) Replace Bush / Bearing	750
	ii) Rewinding	1900
	iii) Replace New	4500
	iv) Fan Capacitor	325
9	Indoor Blower Motor Rewind	
	i) (5 H.P)	6500
	ii) (10 H.P)	7500
	iii) (15 H.P)	7500
	iv) (20 H.P)	7500

10	Indoor Blower Motor Bearing / Bush Replace	
	Bearing / Bush Replace (5 H.P)	1200
	Bearing / Bush Replace (10 H.P)	1200
	Bearing / Bush Replace (15 H.P)	1500
	Bearing / Bush Replace (20 H.P)	1500
11	Indoor Blower Replace (1 Ton to 2 Ton)	3500
12	Indoor Blower Replace	
	i) (5 HP)	9500
	ii) (10 HP)	9500
	iii) (15 HP to 20 HP)	11500
13	Out Door Fan Motor	
	i) Bearing / Bush Replace	1200
	ii) Rewinding (1 Ton to 2 Ton)	2500
	iii) Replace New	5500
14	Out Door Repair	
	i) Service Valve	1800
	ii) Running Capacitor	1850
	iii) Magnetic Contactor	1525
	iv) Fan Blade	1100
	v) Fan Capacitor	350
	vi) Strainer Filter	275
	vii) Gas Valve ½, ¼, 3/8, 5/8, ¾ Ton to 2 Ton)	750 (each)
15	Out Door Repair (5H.P to 20 H.P)	
	i) Magnetic Contactor (Motor)	2500
	ii) Magnetic Contactor (Compressor)	3500
	iii) Overload	1900
	iv) Timer	2900
	v) Fan Blade	3500
	vi) LP & HP Switch	4500
	vii) Phase Failer (Adviser)	2600
	viii) Drier Filter	1300
	ix) Fan Capacitor	450
	x) HVAC Service Valve	985
	xi) Oil Valve	875
16	Out Door Fan Motor Bearing / Bush Replace	
	i) (5 HP)	1200
	ii) (10 HP)	1200
	iii) (15 HP to 20 HP)	1500
17	Out Door Fan Motor Rewinding	
	i) (5 HP)	5000
	ii) (10 HP)	5500
	iii) (15 HP to 20 HP)	7500
18	Out Door Fan Motor Replace	
	i) (5 HP)	7500
	ii) (10 HP)	16000
	iii) (15 HP to 20 HP)	18000

19	Extra Copper Pipe Charges with Control Wire Insulation (1 Ton to 2 Ton)	690 (PRFT)
20	Extra Copper Pipe Charges with Control Wire Insulation	
	i) (5 HP)	980 (PRFT)
	ii) (10 HP)	1150 (PRFT)
	iii) (15 HP to 20 HP)	1250 (PRFT)
21	Copper Pipe Insulation with Tape PRFT	75 (PRFT)
22	Dismantling of Air Conditioner (1 Ton to 2 Ton)	1500
23	Dismantling of Air Conditioner (5 HP to 20 HP)	2500
24	Installation of Air Conditioner (1 Ton to 2 Ton)	2500
25	Installation of Air Conditioner (5 HP to 20 HP)	7500
26	Replacement of New Compressor (1 Ton)	
	i) (Piston)	25000
	ii) (Rotary)	25000
27	Replacement of New Compressor (1.5 Ton)	
	i) (Piston)	29500
	ii) (Rotary)	29500
28	Replacement of New Compressor (2 Ton)	
	i) (Piston)	39000
	ii) (Rotary)	39000
29	Replacement of New Compressor (5 HP)	
	i) (Piston)	98000
	ii) (Scroll)	105000
30	Replacement of New Compressor (10 HP)	
	i) (Piston)	150000
	ii) (Scroll)	165000
31	Replacement of New Compressor (15 HP)	
	i) (Piston)	165000
	ii) (Scroll)	195000
32	Replacement of New Compressor (20 HP)	
	i) (Piston)	195000
	ii) (Scroll)	215000
33	Remote Control All Model (1 Ton to 2 Ton & 5 HP)	2750
34	Fan Belt for Blower Motor (5 HP to 20 HP)	1275
35	Flare Nut 1/2, 1/4, 3/8, 5/8, 3/4,	95 (each)

36	Iron Frame with Fitting	
	i) (1 ton to 2 Ton)	1500
	ii) (5-HP)	2500
37	Drain Pipe PVC (PRFT)	29 (PRFT)
38	AC Evaporator Repair (Indoor)	
	i) (1 Ton to 2 Ton)	3500
	ii) (5 HP to 20 HP)	4800
39	AC Evaporator Replace (Indoor)(New)	
	i) 1 Ton	9000
	ii) 1.5 Ton	11500
	iii) 2 Ton	15900
40	AC Expansion Valve (5 HP to 20 HP)	12500
41	Compressor Oil for AC Compressor (Per Litter)	1200 (Per Litter)
42	Indoor & Out Door Capillary Tube PRFT	98 (PRFT)
43	Outdoor Condenser Repair	
	i) 1 Ton	2900
	ii) 1.5 Ton	3500
	iii) 2 Ton	4500
44	Outdoor Condenser Repair	
	i) 5 HP	8000
	ii) 10 HP	12000
	iii) 15 HP	12000
	iv) 20 HP	15000
45	Outdoor Condenser Replace	
	i) 1 Ton	9500
	ii) 1.5 Ton	13500
	iii) 2 Ton	17500
46	Outdoor Condenser Replace	
	i) 5 HP	55000
	ii) 10 HP	105000
	iii) 15 HP	115000
	iv) 20 HP	125000
47	Compatible Outdoor Unit complete	
	i) 1 Ton	30000
	ii) 1.5 Ton	35000
	iii) 2 Ton	42000
	iv) 5 H.P	165000
48	Compatible Indoor Unit complete	
	i) 1 Ton	15000
	ii) 1.5 Ton	18000
	iii) 2 Ton	29000
	iv) 5 H.P	85000

49	A.C Invertor	
	i) 1 Ton	98000
	ii) 1.5 Ton	135000
	iii) 2 Ton	185000
50	A.C Invertor Compressor (Rotary)	
	i) 1 Ton	39000
	ii) 1.5 Ton	48000
	iii) 2 Ton	75000
51	A.C Invertor Kit Repairing (Indoor & Outdoor)	22000
52	A.C Invertor Indoor Motor (Rewinding, Repairing & Replacement)	9800
53	A.C Invertor Outdoor Motor (Rewinding, Repairing & Replacement)	11500
54	A.C Invertor Kit Replacement (Indoor & Outdoor)	38000
55	A.C Invertor Gas Charging R410 & R134	7500
56	Chigo DC Inverter VRF System (5 HP To 20 HP)	2000 As per unit charges
Grand Total		3408127